Approved For Release 2000/04/13 : CIA-RDP68B00320R000100070004-1

FORM 124 USE PREVIOUS EDITIONS MFG. 1-65

DATE

ROUTING

1	comm	9	KB
2	"	10	
3	ND	11	
4	"	12	
5	DCA	13	
6	file	14	
7	Initial	15	
8	DDSA	16	

TO :

FROM :

ACTION:

INFO :

IN 55635

25X1A OSA 1-20 5 SW

TO INFO CITE

T O P S E C R E T 150436Z CITE [redacted] 7007

IMMEDIATE [redacted] INFO [redacted]

C136

25X1A 25X1A 25X1A

ATTN [redacted] 25X1A

1. FYI, FOLLOWING IS BRIEF RESUME BW ACTIVITY LOGGED [redacted] AS OF 0423Z: 25X1A

0156Z	A OK
0159	ONE CHIRP - NO APPARENT CAUSE
0220-0344	NUMEROUS VOICE CALLS
0344	UNREADABLE
0352	POSSIBLE A OK
0353	UNREADABLE, POSSIBLY EGT 325-500
0354	UNREADABLE
0355	UNREADABLE
0355	IFF OFF
0358	L60M, EGT 325-500, AC GEN OFF
0402	UNREADABLE
0403	L50M, EGT L325, RPM L75 PERCENT
0413	L40M, OXY SEC AND PRI OFF
0420	UNREADABLE

2. ALL SIGNALS FROM ARTICLE WEAK TO VERY WEAK WITH BEST READOUTS BEING OBTAINED ON PNA-7 ANTENNA. FOREGOING SUGGESTS POSSIBLE LOSS OF POWER IN POWER AMPLIFIER STAGE OR ERRATIC ANTENNA TUNER OPERATION.

T O P S E C R E T TOR 0536Z 15 MAY 66

EDD
PI
RP
KB
DB
AF
NM
DJ

[redacted]

GROUP 3
EXCLUDED FROM AUTOMATIC DOWNGRADING AND DECLASSIFICATION

Approved For Release 2000/04/13 : CIA-RDP68B00320R000100070004-1
REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. COPY NO. 7